
SECTION VIEW



Note: low water mark: flats are virtually empty of water during winter months or after extended North wind.

Approx 74 cu. yds of fill .
necessary. curve of shoreline
reduced 25ft to 0ft as
bulkhad reaches shore


Top 2000ft2

Submitted by RON Dowty June 13,07




PLAN VIEW #1

Unnamed mudflats



Application of RON Dowty





JANE DOWTY

BOUNDARY SURVEY OF Lot 1 of River Morsh Estates, a subdivision in Lat 4 of Section 30, Township 9 South, Range 8 West, as per plat recorded in Plat Book 38, Page 157, records of Calcasieu Porish, Louisiana

REGISTERED PROFESSIONAL LAND SURVEYORS Louisiana, Texas, Arkansas,

Mississippi & Alabama

Office: 337-439-5808 Fax: 337-439-3339

815 Mulberry Street Westlake, LA 70669

DATE:	SCALE:	NOTES:	DRAWN BY:	CHECKED BY:	JOB NO.:	PLAT No.:	THIS SURVEY MEETS THE MINIMUM REQUIREMENTS FOR A
6-23-06	1" = 50'	File	GAE	GAE	206294	206294.dwg	CLASS "_C_" SURVEY ACCORDING TO THE "LOUISIANA MINIMUM STANDARDS FOR PROPERTY BOUNDARY SURVEYS."